

201110" E06E400F

Fushang, Holly, Rochester, Lang & Co. Inc., P.C.
 767 Third Avenue, New York, NY 10017-2023
 Atty. Docket No. 02010/HG NAKAJIMA et al

Fed. No. (212) 319-4900

1/15

FIG. 1




FIG. 2




FIG.3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10





FIG. 11



10043903.011102

FIG.12




FIG.13





FIG.14

STRAIN MEASURING POSITION

(SECTION ON BROKEN LINE)



PROBABLE FRACTURING PORTION

(POSITION OF MARK X ON SIDE WALL PORTION)

FIG.15

